

FLOATING SEAL RING ACTING AS A THIRD BEARING

Case History


Presented by:
Sherif Mekawey, Principal Engineer
Machinery Management Services
GE – Bently Nevada
Abu Dhabi

February 2011




Background

- The synthesis Gas Compressor was recently overhauled.
- Replaced the IP Compressor rotor, interstage seals and floating seal rings.
- Replaced the Inboard radial & thrust bearings of IP Compressor.
- When the machine started, high vibration was experienced on the Inboard bearing while Outboard bearing indicated low vibration levels.





Data collected during steady state





Y: Comp I/B V-201 45° Left DIR AMPL: 2.55 mil pp
X: Comp I/B V-202 45° Right DIR AMPL: 2.50 mil pp
MACHINE: IP Compressor
01AUG2001 06:30:47.5 Steady State DIRECT

Direct Orbit/Timebase Plot




: Comp IB V-201 45° Left VECTOR: 2.32 mil pp 283°
: Comp IB V-202 45° Right VECTOR: 2.31 mil pp 26°
MACHINE: IP Compressor
MAUG2001 06:30:47.5 Steady State 1X UNCOMP

Filtered Orbit/Timebase Plot



POINT: Comp IVB V-201 $\angle 45^\circ$ Left DIR AMPL: 2.55 mil pp
POINT: Comp IVB V-202 $\angle 45^\circ$ Right DIR AMPL: 2.50 mil pp
MACHINE: IP Compressor MACHINE SPEED: 9361 rpm
01 AUG 2001 06:30:47.5 Steady State
WINDOW: None SPECTRAL LINES: 400 RESOLUTION: 0.032X

Full Spectrum Plot




REV VIB COMPONENTS

CW ROTATION


FWD VIB COMPONENTS

Data collected during shutdown



Shutdown Polar Plot

POINT: Comp I/B V-201 $\angle 45^\circ$ Left 1X COMP SR: 0.437 $\angle 131^\circ$ 2.72 $\angle 288^\circ$ @9361 rpm
MACHINE: IP Compressor
From 01AUG2001 06:30:47.5 To 01AUG2001 08:00:03.6 Shutdown




Shutdown Bode Plot


POINT: Comp I/B V-201 $\angle 45^\circ$ Left 1X COMP SR: $0.437 \angle 131^\circ$ $2.72 \angle 288^\circ$

MACHINE: IP Compressor

From 01AUG2001 06:30:47.5 To 01AUG2001 08:00:03.6 Shutdown 9361 rpm




Symptoms of the Problem



Symptoms:


- Vibration amplitude did not peak at the designed balance resonance speed of 5700 rpm
- The amplitude kept changing as the square of the speed changed from 5000 rpm to 9200 rpm.



Symptoms:

- The phase angle also did not change while passing the designed balance resonance speed

POINT: Comp I/B V-201 $\angle 45^\circ$ Left 1X COMP SR: 0.437 $\angle 131^\circ$ 2.72 $\angle 288^\circ$ @9361 rpm
MACHINE: IP Compressor
From 01AUG2001 06:30:47.5 To 01AUG2001 08:00:03.6 Shutdown



All these symptoms prove that the balance resonance speed has increased to beyond operating speed.

Analysis

- In general, the rotor's balance resonance speed is a function of the rotor mass and spring stiffness.
- It will remain unchanged unless the rotor mass or spring stiffness changes. A simple formula that describes this relationship is:

$$\omega_{res} = \sqrt{\frac{K}{M}}$$

Where:

ω = rotor natural resonance frequency

K = system spring stiffness

M = rotor mass

The rotor mass probably did not change.
It is now obvious that the system spring
stiffness had increased.

**What could have increased the
spring stiffness?**

~~Severe Misalignment!~~

- The coupling is flexible type
- The orbit shape doesn't suggest misalignment

Rub!

What can cause Rub?

~~Interstage seal rub!~~

- Shaft will bow
- Vibration will increase on I/B and O/B bearings
- Machine can trip in few minutes


~~Bearing rub!~~

- Tilt Pad Bearing
- Normal bearing temperatures
- Bearing clearance is usually bigger than the seal ring clearances. So, it will rub in the seal area before a bearing rub can occur.
- *Lubricated seal rub is suspected*


CONCLUSION:

*Locked-up seal ring acting as
an additional bearing*

Verification of the Problem



Modal Analysis




POINT: 2YD $\angle 45^\circ$ Right 1X UNCOMP

0 $^\circ$


@ 0 RPM

From 20Mar02 19:59:07 To 20Mar02 19:59:07 TRANSIENT



19999 um pp FULL SCALE

CW ROTATION




POINT: 2YD $\angle 45^\circ$ Right 1X UNCOMP

22.8 $\angle 15^\circ$ @ 10589 RPM


From 20Mar02 19:21:04 To 20Mar02 19:21:04 TRANSIENT

um pp
50.0



50.0 um pp FULL SCALE

CW ROTATION




Rub

Corrective action:


- Increased the seal rings clearance, typically from 0.001 to 0.003 inch (OEM Recommendation)
- Adjusted the anti-rotation pins to allow maximum floating

Data collected during startup




Startup Polar Plot


POINT: IP Comp I/B V-201 $\angle 45^\circ$ Left 1X COMP SR: 1.13 $\angle 169^\circ$ 2.10 $\angle 118^\circ$ @8849 rpm
MACHINE: IP Compressor
From 06AUG2001 07:06:07.4 To 06AUG2001 11:27:04.2 Startup



Y: IP Comp I/B V-201 $\angle 45^\circ$ Left DIR AMPL: 2.85 mil pp
 X: IP Comp I/B V-202 $\angle 45^\circ$ Right DIR AMPL: 1.82 mil pp
 MACHINE: IP Compressor
 06AUG2001 11:17:53.6 Startup DIRECT




POINT: IP Comp I/B V-201 $\angle 45^\circ$ Left DIR AMPL: 2.85 mil pp
 POINT: IP Comp I/B V-202 $\angle 45^\circ$ Right DIR AMPL: 1.82 mil pp
 MACHINE: IP Compressor MACHINE SPEED: 8840 rpm
 06 AUG 2001 11:17:53.6 Startup
 WINDOW: Hanning SPECTRAL LINES: 400 RESOLUTION: 0.017X




REV VIB COMPONENTS

CW ROTATION

FWD VIB COMPONENTS




Data acquired after balancing



Startup Polar Plot


POINT: IP Comp I/B V-201 $\angle 45^\circ$ Left 1X COMP SR: 0.704/ 174° 0.910/ 59° @8820 rpm
MACHINE: IP Compressor
From 07AUG2001 04:40:46.3 To 07AUG2001 08:29:25.8 Startup



2 mil pp FULL SCALE


CW ROTATION

POINT: IP Comp I/B V-201 45° Left TX COMP SR: 1.13/169° 2.10/118° @8849 rpm
MACHINE: IP Compressor
From 06AUG2001 07:06:07.4 To 06AUG2001 11:27:04.2 Startup



Prior to balancing

POINT: IP Comp I/B V-201 45° Left TX COMP SR: 0.704/174° 0.910/59° @8820 rpm
MACHINE: IP Compressor
From 07AUG2001 04:40:46.3 To 07AUG2001 08:29:25.8 Startup



After balancing

CONCLUSIONS:

- The system stiffness increased, due to a locked-up seal ring acting as an additional bearing
- Transient data helped determine the root cause of the problem
- This problem could be misdiagnosed as an unbalance problem

THANKS,
ANY QUESTIONS?

