

VSD Motor Intermittent Vibrations Excursions



Authors


Gertjan Van De Flier-

Rotating equipment Discipline Manager

Asad Anwar Syed

Rotating Equipment Discipline Engineer.

PEARL GTL – INTRODUCTION




- 1.6 Bcf/d of Wet Gas
- 120 kbb/d NGLs/Ethane
- 140 kbb/d GTL products
- \$ 18 – 19 billion investment cost
- Project 100% financed by Shell
- The Largest energy project in Qatar

Compressor/ Driver Details

- **Type/Size/Model- STC-SV, 2 Stage, Barrel Type Cent. Compr.**
- **Driver - Motor 1.4 MW, Driven Through VSD (Variable Speed Drive)**
- **Operating Speed- 12800 RPM**
- **Insulated Motor Bearings , Grounding Unit For Induced Voltages.**

Machine CM Diagram

1K-0562




Problem Statement


- Compressor Drive Motor DE/NDE Bearing vibrations started increasing, from June'12 onwards, without any change in the operating conditions of the machine.
- Compressor & Gear Box were not affected and kept running at normal vibration levels.
- The incident of high motor bearing vibrations started repeating every few weeks initially and slowly the frequency of the incident and vibration amplitude started increasing near to trip limits.
- Trends showed vibrations slowly rising up to and beyond alarm limits, and slowly subsiding and falling back to acceptable, normal limits

Excursion Trend

Ad-Hoc Trend



Typical Sample Excursion



Motor Grounding Unit



Grounding Unit Carbon Elements



Carbon Elements For Grounding




Observations

- **Grounding fitted with 2 pairs of carbon elements.**
- **One of the element pairs found snapped off.**
- **Carbon elements oriented at bottom.**
- **Elements working length within limits.**

Mitigation

- **Elements replaced.**
- **Grounding unit orientation changed.**
- **Holding spring tightened to increase the element seating tension.**
- **Grounding cable connections cleaned and retightened.**
- **Grounding unit inspection scheduled in PM list.**

Vibration Trend Jan'12 Onwards



Explanation Of The Phenomenon

- High voltage motors with VSDS, induce parasitic currents/voltages on the Rotor.
- Motor Rotor gets magnetized, overtime, if not grounded properly.
- GB/Comp. high impedance, insulated motor bearings, and absence of proper grounding connection prevents induced parasitic currents/ voltages to go to earth.
- Electromagnetic forces having same rotational frequency as of rotor, led to an unbalanced rotating magnetic field.
- The rotating magnetic field interacting with static magnetic field, resulted in unbalance in the rotor and led to high vibrations.
- The amplitude of vibrations depended on the magnitude of unbalanced electro magnetic forces.

Explanation Continued

- Vibrating Motor rotor got de-magnetized, due to grounding connection establishing during vibrations/ excursions/jerks .
- De-magnetization of Rotor, reduces vibrations back to normal.
- Magnetization & de-magnetization cycle kept repeating till the grounding connection was rectified.
- Vibration came to normal after 10 days of carbon element replacement. This is run-in-effect of the new elements , to build up a new patina at the slip ring surface.

